

No.	Regist	Name	Built	Year O	Year O	Scrapp	Other
	EZ 88 598	Volvo B58-55 / Aabenraa M67	1968	1974	1978		Door position 1-0-2.
2 0 1 3	AX 92 497	FIAT 308 / Ringsted	1970	1970	1980	1981	
2 0 1 8	AX 94 070	FIAT 308 / Ringsted	1970	1971	1980	1981	
2 0 0 5	AX 97 603	FIAT 308 / Ringsted	1970	1970	1980	1981	
2 0 0 1	HS 95 855	FIAT 308 / Ringsted	1970	1970	1980	?	
2 0 0 7	BJ 90 309	FIAT 308 / Ringsted	1971	1974	1980	1981	
2 0 1 1	BC 88 665	FIAT 308 / Ringsted	1971	1971	1980	1981	
2 0 0 9	CB 95 205	DAB LIDRT 12/2 (5)	1973	1973	1980	1985	
2 0 2 0	EZ 91 195	DAB LIDRT 12/2 (5)	1973	1973	1980	1986	
2 0 1 7	DD 93 581	FIAT 418 AL / Ringsted	1975	1975	1980	?	
2 0 0 2	CV 91 301	DAB LIDRT 12/2 (5)	1975	1975	1980	1987	
2 0 1 2	DD 88 599	FIAT 418 AL / Ringsted	1975	1975	1980	1983	
2 0 1 6	DD 88 619	FIAT 418 AL / Ringsted	1975	1975	1980	1983	
2 0 2 1	DV 90 768	FIAT 418 AL / Ringsted	1976	1976	1980	?	
2 0 2 2	DX 92 879	FIAT 418 AL / Ringsted	1977	1977	1980	?	
2 0 2 3	DY 95 981	FIAT 418 AL / Ringsted	1977	1977	1980	?	
2 0 0 3	EE 91 978	DAB LS 575-680/2 (1)	1977	1977	1980	1989	
2 0 2 4	EE 91 979	DAB LS 575-680/2 (1)	1977	1977	1980	1989	
2 0 1 4	ER 92 259	DAB LS 575-690/2 (1)	1978	1978	1980	?	
2 0 1 5	ER 92 260	DAB LS 575-690/2 (1)	1978	1978	1980	?	
2 0 1 0	ER 92 227	DAB LS 575-690/2 (1)	1978	1978	1980	1988	
2 0 0 6	ER 92 258	DAB LS 575-690/2 (1)	1978	1978	1980	1989	
2 0 0 4	ER 92 257	DAB LS 575-690/2 (1)	1978	1978	1980	1989	
2 0 1 9	ER 92 233	DAB LS 575-690/2 (1)	1978	1978	1980		